











									
A	12x	B	12x	C	12x	D	2x	E	4x







2




3





4








5






									
A	10x	B	10x	C	10x	D	2x	E	4x







2




3





4





5










							
16mm		25mm					
A	4x	B	24x	C	5x	D	1x



















 4X35mm							
A	8x	B	4x	C	4x	D	1x









2











3







				
A	B	C	D	E
24x	24x	24x	2x	8x
				16mm









(CZ) Směr vyznačený trojúhelníkovou šipkou je rovnoběžný se šroubem.
 (SK) Smer vyznačený trojuholníkovou šípkou je rovnobežný so skrutkou.
 (PL) Kierunek wskazany przez trójkątną strzałkę jest równoległy do śruby.
 (DE) Die durch den dreieckigen Pfeil angegebene Richtung verläuft parallel zur Schraube.







3






4
















				
A	B	C	D	E
46x	46x	46x	2x	8x
				16mm







6 762x50x15 1x









(CZ) Směr vyznačený trojúhelníkovou šípkou je rovnoběžný se šroubem.
 (SK) Smer vyznačený trojuholníkovou šípkou je rovnobežný so skrutkou.
 (PL) Kierunek wskazany przez trójkątną strzałkę jest równoległy do śruby.
 (DE) Die durch den dreieckigen Pfeil angegebene Richtung verläuft parallel zur Schraube.




























								 16mm									
A	32x	B	32x	C	32x	D	2x	E	42x	F	4x	G	4x	H	2x	I	1x



4*8mm
J
4x



























6












C 32x







A

40x




B

40x




C

40x




D

2x



E

42x



F

4x



G

4x



H

2x




I


1x




J



4x
















(CZ) Směr vyznačený trojúhelníkovou šípkou je rovnoběžný se šroubem.
 (SK) Smer vyznačený trojuholníkovou šípkou je rovnobežný so skrutkou.
 (PL) Kierunek wskazany przez trójkątną strzałkę jest równoległy do śruby.
 (DE) Die durch den dreieckigen Pfeil angegebene Richtung verläuft parallel zur Schraube.









5








6








					
	6X20mm		4X35mm		
A	2x	B	2x	C	4x



1



2

